IPNext600™
NGN IP-PBX System
High Performance Fault Tolerant IP-PBX Solution

NAT Traversal Service for SIP Port Blocking Issue Solving

AddPac Technology

2011, Sales and Marketing

www.addpac.com

Contents

- Network Diagram

- IP Telephony Service Environment

- NAT Traversal Service

    - Call Established Mode

    - Change Session Mode

- Smart Multimedia Manager Configuration

AddPac

Network Environment

Inbound UDP Port 5060
Is blocked by ISP

IP Network

SIP Terminal

SIP ALG
(Application-Level Gateway)

ISP

**IPNext600
NGN IP-PBX**

SIP Terminal

IP Telephony Service Network Environment

- Terminal : IP Phone, VoIP Gateway, etc
  - Located below the NAT
  - Do not support RFC3581 (An Extension to the SIP for Symmetric Response Routing)

- NAT : SOHO Router
  - SIP ALG(Application-level gateway)
    - Replace IP in "Via" header with the public IP and port
    - Replace "Contact" with mapped public IP and port
    - Replace SDP media address with public IP and port
  - In some network environments, the SIP ALG replace "Contact" port in REGISTER message only. It's caused by wrong configuration or abnormal operation.

- Network : ISP Network
 - Inbound UDP port 5060 is blocked by local ISP

[Call Established]

INVITE
Via : SIP/2.0/UDP 192.168.1.10 :5060
Contact :<SIP:1000@192.168.1.10>

(1)

INVITE
Via : SIP/2.0/UDP 60.17.196.2 :5060
Contact :<SIP:1000@60.117.196.2>

(2)

IP Network

INVITE

(3)

SIP Terminal which
does not support
RFC3581 'rport'
Source IP :192.168.1.10
Source Port : 5060

SIP ALG
Source IP : 60.17.196.2
Source Port : 49163

ISP

Inbound UDP Port 5060
Is blocked by ISP

**IPNext600
NGN IP-PBX**

SIP Terminal

AddPac

[Change Session]

Re-INVITE
Destination IP : 60.17.196.2
Destination Port : 49163
 (2)' Force NAT Traversal enabled

Re-INVITE
Destination IP : 192.168.1.10
Destination Port : 5060

Re-INVITE
Destination IP : 60.17.196.2
Destination Port : 5060

Re-INVITE

(3)

(2)

(1)

IP Network

SIP Terminal which
does not support
RFC3581 'rport'
Source IP :192.168.1.10
Source Port : 5060

SIP ALG
Source IP : 60.17.196.2
Source Port : 49163

ISP

**IPNext600
NGN IP-PBX**

SIP Terminal

Inbound UDP Port 5060
Is blocked by ISP

AddPac

Smart Multimedia Manager Configuration

- Smart Multimedia Manager
  - Device Management
    - Devices
      - Server
        » (IPNext) Properties

- Check 'Force NAT Traversal' option

AddPac

Thank you!

AddPac Technology Co., Ltd.
Sales and Marketing

Phone +82.2.568.3848 (KOREA)
FAX +82.2.568.3847 (KOREA)
E-mail sales@addpac.com